

*Congratulations on your purchase of marlanteak outdoor furniture. We trust it will provide you with many years of exceptional comfort and service. Take a few minutes to read through the relevant sections of this care instruction sheet to find out how you can maximise the lifespan of your investment and keep it looking great for generations to come.*

## **BATYLINE/SLING**

**TRIBU, GLOSTER**

*Ranges: Natal Light, Neutra, Mystral, Asta*

The Batyline® mesh used in the Neutra and Natal Light ranges is an extremely durable and high quality material.

Batyline® is a French made material consisting of a polyester fiber covered by a coating of PVC making it nearly impossible to tear. It is 100% synthetic, resistant to rot, mildew and UV radiation. Sagging is minimal as it has a maximum stretch of 3% and a "memory" - it will slowly stretch back to its original shape after it has been used. Batyline® is very easy to maintain and can easily be cleaned with soap and water.

Textilene: The textilene sling consist of a coated polyester weave, like Batyline. Simply clean With soap and water and rinse thoroughly with water. Do not use salt or chlorinated products because they may attack the hardware used to secure the straps.

Sling: Gloster's Textilene woven vinyls are resistant to fading, mildew and wear & tear under even the most severe weather conditions. Sling requires only occasional cleaning with a non-foaming cleaner like Gloster Sling & Woven Cleaner to keep it looking as good as new.

## **GUARANTEES AND REPAIRS**

All items from the Classic Teak range are guaranteed for five years, whereas all Kettal, Tribu , Gloster, Rausch and Roda furniture is guaranteed for two years against defects/manufacturing faults. Please keep your invoice for guarantee purposes.

We will happily repair or, if necessary, replace items under guarantee. Defective items need to be returned to our head office in Cape Town for the necessary repairs to be effected. All transport cost are the client's responsibility. Where items have been damaged due to misuse, negligence or other causes, such as wind damage, repairs will be charged for.